


Warning: To avoid the potential risk of fire and shorting, under any circumstances **should not** you use the connectors and end cap **without** busbar stoppers (Drawings below with "X" mark) for your track system.




INSTALLATION INSTRUCTIONS

INSTALLATION INSTRUCTIONS-ADJUSTABLE T CONNECTOR

TAKE THIS ADJUSTABLE T CONNECTOR TO CONNECT THREE TRACK SECTIONS INTO FOLLOWING TURNS: 1) RIGHT "T" TURN.
2) LEFT "T" TURN.

CAUTION-Turn off switch at main power source before installing any track or fitting.

1. Loosen set screw and insert connector with Embossed Polarity Arrow (Polarity side of two fingers-Grounding contacts) pointing to Debossed Track polarity line for proper installation. (RIGHT "T" TURN)
2. **NOTE:** If the connector can not be installed properly and easily, do not force. Remove T cover from fitting. Adjust the direction of fitting to be an opposite "T" (LEFT "T" TURN) and try to connect three tracks by step (1) until it can be connected for proper installation.
3. Tighten set screw to lock to track. **NOTE:** Track ends must be terminated with either a dead end or a connector. Replace T cover on fitting and tighten cover screw.



SAVE THIS INSTRUCTIONS